




## Schuko connector body L/N poles protection cover user instructions.

Tools	Explanation
	Cutter knife PH2 Phillips Screwdriver Steel ruler
Photos	Explanation
	<ol style="list-style-type: none"><li>1. Lay the blade or ruler flat, as shown on the red circle in the left.</li><li>2. Slowly push up the L/N poles cover in the direction by the arrow.</li></ol>
	<ol style="list-style-type: none"><li>1. Use a PH2 Phillips screwdriver to loosen the L/N/E pole screws counterclockwise.</li><li>2. Insert the Spade Terminal of the front end of the cable into the corresponding pole of the body.</li></ol>



1. Use a PH2 Phillips screwdriver to tighten the L/N/E pole screws clockwise.
2. Use a digital multimeter to test continuity.
3. Put on the L/N poles cover.



Finished.